



Fig. 12





INSTRUCTIONS FOR INSTALLING COMPRESSION "H" TAP CONNECTORS

- 1. Use these connectors for non-tension splice or tap connections of aluminum to aluminum conductors or of aluminum to copper conductors, as shown above.
- 2. Be sure to use the correct size connectors and tooling as per manufacturers recommendations.
- 3. Install the connectors so that the aluminum or ACSR conductors are physically above the copper conductors.
- 4. Strip conductor as shown above, wire brush until metal is clean. Apply anti-oxidant compound and make connection **immediately**.

CAUTION: Do not nick or cut conductors in stripping process!

- 5. Place stripped conductor in groove, allowing it to extend 1/2" beyond connector from end to end using full number of indents as per manufacturers recommendations.
- 6. Tape all connections.

